

#5420 - Parcel #3884

Owner: Dorothy L. Melter

Main Island (continued)

Winter Cabin: 19' x 33' - vertical leg construction; gable roof with roll asphalt covering. Floor plan consists of a large front porch, a kitchen-living area, and two separate bedrooms. Floors are pine boards; the kitchen area is covered with congeum. Windows are of the casement type, with screens, with additional light being provided by sky lights. This unit is heated by a barrel stove. No plumbing facilities, sinks, etc., are provided. This unit is in good condition. ✓

Guest Cabin: 13' x 25' - horizontal hewed leg construction; gable roof, with roll asphalt covering. Floor plan consists of two rooms; the front porch, which also doubles as the kitchen, and the main portion of the cabin, which serves as the sleeping and living quarters. Floors are of pine boards covered with congeum. Heat is supplied by barrel stoves. Windows are of the casement type with screens provided on some units. The unit also has one sky light. No plumbing facilities, sinks, etc., are provided. This unit is in good condition. ✓

Storage & Warehouse: 9' x 14' - horizontal hand hewed leg construction; shedtype roof covered with roll asphalt roofing. Hand hewed plank floor. This building is in fair condition. ✓

Ice House: 12' x 13' - round horizontal leg construction; gable roof covered with roll asphalt. This building is in fair condition. ✓

Fish Cleaning House: 6' x 10' - upright pole construction, average 3" caliber; board roof, overlapped; screened windows; board floor. The building is in fair condition. ✓ *Gone*

Man Cabin: (on western tip) 19' x 27' - vertical hand hewed leg construction; gable roof covered with asphalt roll roofing; pine board floors, covered with congeum in kitchen; casement type windows, some with screens. Floor plan consists of front porch, combination kitchen and living area, and two bedrooms. Heat is supplied by barrel stoves. No plumbing facilities, sinks, etc., are provided. This unit is in good condition. ✓

Boat House: 10' x 12' - This is of rock and leg construction, built into an embankment off of the lakeshore. The roof is dirt covered. The unit is still very functional and in good condition. ✓ *Gone*

Island No. Two (1 acre):

Menyreen Cabin: 13' x 24' - This is of horizontal leg construction; gable roof covered with roll asphalt roofing. Floor plan consists of a front porch, which doubles as a kitchen, and a combination sleeping and living room. Windows are of the casement type, some being provided with screens. Floors are wood, congeum covered. Heat is supplied by a barrel stove. This unit is in good condition. ✓